# Nokeval

No 270503

# **User's Manual**

Model 2041 for strain gauge sensors



# Index

General	3
Technical specifications	4
Dimensions	
Terminal connections	
Front panel and keys	6
Configuration	7
Configuration parameters	
Output 0/4-20 mA and 010 V (option)	9
Output connections	
Alarm (option)	
Alarm relay connections	10
Serial output RS-485/RS-232 (option)	11
Serial output connections	11
Serial communication	
Serial protocol (SCL)	
Secret code	
Panelmeter 2000 construction	14
Modular indicator series 2000	15

### Manufacturer:

### Nokeval Oy

Yrittajakatu 12 FIN-37100 NOKIA Tel. +358 3 342 4800 Fax. +358 3 342 2066

## 2041 Panelmeter for strain gauge sensors

- · Strain gauge sensors with 4- or 6 -wire connection
- Excitation voltage 10V to sensors, max 150 mA
- 6-digit processor-based LED-display
- Settings via front panel keys
- Output 0/4..20 mA, 0..10 V
- Serial output RS-232 or RS-485
- 2 4 alarm relays
- · Display taring via front panel key
- Measuring accuracy < 0,05 % of span</li>
- Power supply 85..240 VAC or 12..32 VDC/ 24 VAC

The versatile panelmeter 2041 is designed for strain gauge sensors. Strain gauge sensors can be connected with 4 or 6 wires. The 6-wire connection removes the lead wire resistance, as bridge voltage is measured from the sensor poles, and therefore it is recommended for applications requiring very high accuracy. The panelmeter provides 10 V excitation voltage for sensors, max. four 350 ohm sensors. Options to the 2041 include output 0/4-20 mA , 0-10V, 2..4 alarms or serial output RS-485/232.

Display scaling and taring is easy via front panel keys. Scaling can be carried out in two different ways, either by applying the mV values of the bridge or using the teaching function. The teaching is done by first loading the sensors with the min. weight and then with the max. weight, after which the meter w i l l l l automatically count the scaling.

In applications where the sensor loading is not in balance a separate serial connection unit of the sensors 20 SA-4 can be used to prevent the nonlinearity caused by the imbalance. There are two power supply alternatives: one for line voltage 85..240 VAC and the other 12..32 VDC/ 24 VAC, both

galvanically isolated from input and output. Analog conversion is done by a 16-bit AD-converter (resolution 1/ 64000) and the number of measurements is 3 per second. Separate passwords can be set for access to the configuration menu and alarms. The display can be damped with a digital filter if necessary. The number of decimals on the display is selectable. Front panel protection rating is IP65.

The panelmeter series 2000 is very flexible and easy to modify by changing input cards for different kinds of sensors, such as temperature sensors, pulse sensors, serial inputs etc. The modification does not require any calibration. The optional cards are the same for all the instruments in this product family. Each panelmeter type has its own datasheet.

Separate field enclosures can be supplied for 1 to 3 panelmeters. The 2041 is also available in the field display series, model 2800-2041.



3



### **Technical specifcation:**

Sensor Sensor connection Bridge connection Bridge supply Measuring range Sensitivity settings Accuracy Repeatability Temperature drift <b>Output (option):</b> Outputs Output range range,	strain gauge, max 350W parallel 4- or 6 -wire connection full bridge or half bridge 10 VDC, max. 150 mA 2550 mV mV/V, freely selectable <0,05 % FS <0,02 % of span 0,0028 % /°C 020 mA, 420 mA and 010 VDC scaleable on the whole display	<b>General:</b> Display range digit selectable Display scaling Display taring Teaching function Configuration Case Front panel protect Operating temp. Terminals Power supply	6 digits, bright red (or green) LED , height 14,5 mm, brightness on the whole range via front panel via front panel keys applying min/max weights via front panel keys 96 x 48 x 110 mm tion IP65, with a rubber gasket 060 °C detachable, max. 1,5 mm <sup>2</sup> 85240 VAC or 1232 VDC / 24VAC
Accuracy Galvanic isolation Load resistance	scaling via front panel 0,05% of the scaled display range test voltage 2000 VDC maximum 700W	Weight	240 g
			2041-001-ILL2-240DC
Alarms (option): Relays prevent	24 alarm relays, max 230 VAC / 2A Optional cards 2000-REL2 or 2000- REL3, 4 relays (2x 2000-REL2) the use of other options	Type Output OUT Alarm card REL2 Power supply: 85240VAC or	
Serial output (opt	ion):	1232 VDC/24 VAC	>
Serialoutput	RS-232 and RS-485 Only for measurement reading or setting of alarms	<b>Optional cards</b> (2 Output card	options available at a time): 2000-OUT
Baudrate	300, 1200, 2400, 4800, 9600 or 19200	Alarm card, 2 relay Alarm card, 3 relay Serial output, RS-2	rs 2000-REL2 rs 2000-REL3 32/485 2000-RS

(When ordering a panelmeter, the "2000" of the cards is left out.)

The panelmeter ia also available with a green LED display: please specify 2041GR in the order code.





#### Connecting bridge sensor with 4- or 6- wires:

Bridge sensors exitation voltage is measured directly from sensor poles. Processor corrects display value if voltage differs from 10 Volts. Selected 6-wire connection technique enables also use of separate voltage supply which voltage may vary between 7..13 V. Unit accepts also 4-wire connection but then the sense wires must be connected to voltage supply terminals (short cut 5-6 and 1-2). This 4-wire connection can be used if the accuracy demand is unimportant or if the sensor lead wire error is corrected by rescaling the display with known error.

If the sensror is not connected with 6-wires the lead wire resistance will reduce the exitation voltage and display shows too low values. How big this error is depends on the current level in wires and on line resistance.

An example: If the line resistance on each sensor is 2 ohms it means that four 350 ohm bridges in parallel causes 87,5 ohm load to 10 V exitation voltage.

#### Half bridge connection:

Model 2041 accepts also half bridge sensor. This is an optional function which must be specified when ordering the unit. Unit which is ordered for half bridge sensor can be used with full bridge connection by replacing the short cut jumber as drawn below.



#### 4-wire connection



#### Bridge sensor

Sensor current can be calculated as: 10V/87,5 ohm =114,2 mA. Voltage in bridge poles is then: 10V-(114,2 mA x 2 ohm)=9,776V.

Sensor message is 2,24 % too low compared to 10.000V exitation voltage. Bridge exitation voltage is directly comparable to received mV-input and vice versa. Model 2041 has continuous exitation voltage measurement function and therefore voltage don't have to be exact in bridge poles.

Half bridge connection in below picture. Terminal 3 is not connected. Sensor cable protective sheath is connected only in one point into terminal 1.





### Front panel and keys



#### **Display Tare procedure:**

Press and hold right arrow (>) until display shows 0000 (approximately for 3 s). Display is tared and ready to measure.

#### Configuration

You can enter configuration stage by pressing two seconds  $\blacktriangle$  and  $\bigstar$ -keys at same time. In program stage f. ex. scaling of display, sensor selection and alarm mode are chosen.

See closer in chapter programming.

#### Setting of alarms

By first pressing of  $\succ$  key you can see setpoint of alarm one (A1), correspondingly by second pressing setpoint of alarm two (A2) etc. Third pressing returns display to normal stage. Alarm indication light blinks showing that alarm has been set (if you do not touch keys you come to normal stage automatically).

When indication light blinks (A1 or A2) you can change alarm value by pressing  $\blacktriangle$  and  $\triangledown$  key. You may have optional alarm relays for each alarm level. Alarm mode, hysteresis and other settings must be set in configuration menu. If you do not touch keys during 8 seconds display returns to normal state automatically and save settings.



### Configuration

You can enter configuration state by pressing two seconds  $\blacktriangle$  and  $\bigstar$  keys at same time. By arrow keys  $\blacktriangle$  and  $\blacktriangledown$  you can move upwards and downwards in main menu. By pressing  $\succ$  key you can enter configuration state at wished point. From setting state you can skip direct to save state or to previous level with  $\star$  key. You may set alarms in configuration or in display stage. Alarm levels can be set in configuration state or measuring state. You can cancel changes by selecting text **UnDo** to display and by pressing  $\triangleright$ key. Next page describes in more details configuration functions.



### **Configuration parameters**

#### Sense

Typical sensor sensivity is 2 mV/V which you will find in label of sensors. Change SET value according to sensivity of sensors. Changing this value will have reserved effect on display. For example changing default selecetivity 2 mV/V to 2,2 mV/V, display reading will reduce 10%.

Measuring range is defined from selectivity as follows Sensor selectivity 2 mV/V is multiplied with the bridge voltage. If selectivity is 2 mV/V and the bridge voltage is 10 V the input measuring range will be  $20 \text{ mV} (2 \text{ mV/V} \text{ V} \times 10 \text{ V} = 20 \text{ mV})$ .

#### Load: Set or Teach

You can make scaling by two different ways as follows: **SET** selection indicates the weighing value which gives the maximum signal from the bridge. Unit uses this value to calculate the maximum mV-signal with maximum load on sensor. If display value is e.g. 5% too low you can fix the display by increasing the Load value 5%.

**Teach** selection gives possibility to use reference loads for scaling, see page 9.

#### Dec

Number of decimals in display. Select 0...5 with stkeys and accept with H-key.

#### Filter

Display filtering. Filtering damps restless display by large number values. Measuring interval is 0,4 s. Value setting between 1(min)..0.010 (max).

1.000 = no filter

0.200 = normal filtering

```
e.g. 0,2 =(1/5) one new value + 4 old values
```

or 0,1=(1/10) one new + 9 old values (very steady)

#### Halt

Display can be set to show zero below Halt value e.g. the display should be showed zero when weighing value is under 10, set halt value 10. You can use also negative values.

#### Bri

Display brightness 1..15 = brightest. Default 7.

#### Output (option)

Output settings. See chapter "Output"

#### Alarm 1 and 2 (option)

Alarm settings. See chapter "Alarm"

#### Serial (option)

Serial output settings. See chapter "Serial output"

#### Code

Secret code settings. See chapter "Secret code"

### Cal

For factory settings

#### Undo, Save

Exit from configuration stage without saving changes (*Undo*) or save and exit (*Save*).

### Scaling of display

Display can be scaled on two different ways.

Select **LOAD** in menu and press ►-key.

- **SET:** Enter display value on max.loading signal from bridge. Example: If sensor gives 2 mV/V and supply voltage for sensor is 10 V, max signal from bridge is 2 mV/V x 10V = 20 mV. If you like to show 5000 for max input signal (20mV), SET value = 5000. The display range is now 0-5000 on input 0-20 mV.
- **TEACH**: You can teach scaling of display by using two reference loads.



### Output 0/4-20 mA and 0..10 V (option)

The display may be provided with isolated output, ranges 0..20 mA, 4..20 mA or 0..10 V, which are programmable.

You can mount output card to slot B or C (default B). Calibration information is saved to card and no calibration is needed in configuration. You need not select card in programming because meter recognizes the mounted card.

Programming: select Output selection in main menu and press ➤ key. See below description.



★-accept and return to main menu



Output 0-10V

6

5

4

3

2

1

Slot B

- (+)

- (-)

0-10V

**Output connections** 

Output 4-20 mA



Slot B

### Alarm (option)

Meter may be provided optional alarm relay card (2000-REL2). In REL2 card is two relays with change over contact. Both relays can be setting in configuration state: alarm level, hysteresis, alarm type and

relay direction. When all alarm settings is done in configuration mode, alarm levels can be easily changed with frontpanel keys in normal measuring state. See chapter "Front panel and keys".



to main menu



### Serial output RS-485/RS-232 (option)

Meter may be provided with optional serial output and you can read measurements by e.g. PC. Display programming can not be made via serial port. Additional card provides serial signal RS232 and RS485, only one of those can be selected.

Serial signal is isolated from both input signal and power supply. Meters with RS485 can be max. 31 in same loop and longest distance 1000m. RS232 enables only connection of one meter and max. distance 10..20 m. In config state you can first select card type (serial) mounted to slot B or C and then address and Baud rate. baud rates are: 300, 1200, 2400, 4800, 9600, 19200 and addresses 0...127.

Program remembers card type mounted, if it has been saved by save command when leaving program. In case you can not choose serial card, slot has automatically recognized card (plug and play).

Main menu



★-accept and return to main menu Serial output RS485 not used

Serial output card installed to the Slot B. Serial address selection 0..127

Baud rate selection





#### **Serial communication**

Baud rate: 300, 1200, 2400, 4800, 9600 and 19 200 1 Start, 8 Data and 1 Stop bit, no parity.

#### Serial protocol (SCL)

MESSAGES: When asking the measurement data from the panelmeter 2041 through the serial port, a command sequence which is in accordance with the SCL protocol is used for the inquiry.

#### <ADDR+80h>COMMAND STRING<ETX><BCC>

#### <ADDR>

The first byte character to be sent contains the address of the destination device and at the same time functions as the start indicator of the command. The uppermost bit of this byte is set, in other words 80H (128 in decimal) is added to the address.

COMMAND STRING: When measurement data is requested, the actual command is: MEA CH 1 ? , in which 1 means the channel number. (there is only one channel in the panelmeter 2041 so the number is always 1).

#### <ETX>

<ETX> mean the end mark of the command, ASCII character 03h.

#### <BCC>

Finally the checksum is calculated using XOR operation on the byte characters of the actual command including the ETX, excluding ADDR byte. In the example the ASCII codes have been presented in hexadecimal.

#### e.g.

One wants the measurement result from the display unit address 1. An inquiry is sent:

MEA CH 1 ? (ASCII codes shown for <BCC> calculation)

M E A C H 1 ?<ETX> <BCC> 4Dx45x41x20x43x48x20x31x20x3F x03 = 6F

(XOR operation is presended with a character x) (ASCII code 20h corresponds to space character)

So the following bytes are sent to 2041: 81 4D 45 41 20 43 48 20 31 20 3F 03 6F

RETURN MESSAGE: The answer from the panelmeter 2041 is obtained in the following format:

#### <ACK>RETURN MESSAGE<ETX><BCC>

#### <ACK>

The first byte of the answer contains the start of the answer <ACK> (ASCII-code 06h) and the answer itself, endmark <ETX> (ASCII-03h) and the checksum of the answer which is calculated from all the byte characters of the answer including <ACK> and <ETX>. 2041 counts the checksum in which case the receiver does not need necessarily to care about it. **e.g.** 

e.g. When a measurement result is for example 21.3, it will be obtained from the panelmeter in the following form

<ACK> 2 1 . 3 <ETX> <BCC>
Answer: 06 32 31 2E 33 03 1B

### Secret code

You can enter secret code by pressing six time keys (1-4) in wished order (lines goes forward in display). Setting must be repeated in same order before new setting is accepted. For example: Press one after another keys  $\blacktriangle \bigstar \bigstar \bigstar \bigstar \bigstar$  and once more  $\blacktriangle \bigstar \bigstar \bigstar \bigstar \bigstar \bigstar$ . You may think the keys as numbers

from left to right 1,2 3,4 in order to help recording and remembering.

e.g.



Input code ▲ ▲ ★ ➤ ▲ ▲ and once more. Example number value would be 113411.

In menu position **Code** press  $\succ$  key and move on to selection state.



 $\star$ -accept and return to main menu

### Panelmeter 2000 construction

The 2000 series panelmeters are modular and easy to assemble. According to customers wishes. The basic construction consists of mother board with tree slots, A, B and C. Slot A determines meter type and provides always input signal. Slot B and C are interchangeable. As factory delivery input signal is always installed into slot A, mA output into slot B and alarms into slot C. In case of f.ex 4 alarms and relay card with 2 changeover contact (2 + 2 relays) are used, you must place

second relay card into slot B. If you

accept only closing or opening relay contacts, you need only one relay card with 4 relays placed into slot C. The slot B is now usable for other optional outputs. You can have different types of meters by only changing the input card in slot A. Data sheet of each type of meter dictates the possible combinations. Recalibration of card is not needed; only scaling and other settings must be set by front panel keys.



Change of meter type: Input card is placed always to slot A. By changing input card you can get an other type of meter. You can change meter with pulse input to meter with current input, thermocouple, strain gage etc.

#### Additional slots:

Additional cards provide output 4..20 mA, alarms, serial interface, BCD output etc. Meter data sheet dictates possible combinations. grey connectors allow line voltage 85..230 VAC (relay contacts).

There are two different mother boards power supply 85..230 VAC and 12..32 VDC. VDCmother board accepts

24 VAC. Connectors are colour coded.

#### Removing meter from case:

Loose connectors and front panel. draw meter out from front. You may remove mother board from rear by opening four screws in corners of case.



Press gently case behind front panel and draw frame outwards gripping upper part of frame.



Yrittajakatu 12 37100 NOKIA, FINLAND Tel. +358 3 342 4800 Fax.+358 3 342 2066

email support@nokeval.com http:// www.nokeval.com